00862.023429 PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: Examiner: Timothy J. Henn

Akitoshi Yamada, et al.) Group Art Unit: 2622

:

Appln. No.: 10/541,381) Confirmation No.: 6303

•

Filed: January 29, 2004) Patent No.: 7,289,141B2

:

For: IMAGE SUPPLY DEVICE,) Issued: October 30, 2007

RECORDING APPARATUS, :

RECORDING SYSTEM, AND December 17, 2008

CONTROL METHOD THEREFOR

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the U.S. Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the U.S. Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However,

the Commissioner is authorized to charge any underpayment or credit any overpayment to

Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by

telephone at (202) 530-1010. All correspondence should continue to be directed to our address

given below.

Respectfully submitted,

/Warren E. Olsen/

Warren E. Olsen

Attorney for Patentees

Registration No.: 27,290

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

Facsimile: (212) 218-2200

WEO/kag

2101465v1

- 2 -

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

7,289,141 B2 PATENT NO.

October 30, 2007 **DATED**

Akitoshi Yamada, et al. Page 1 of 2 INVENTOR(S) :

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 1, "provided with" should read --provided--. Line 18, "provided with" should read --provided--.

COLUMN 6

Line 47, "Dvice Status" should read -- Device Status--.

COLUMN 7

Line 66, "generation" should read --generation of--.

COLUMN 8

Line 30, "interrupted," should read --been interrupted,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. <u>7,289,141 B2</u>

Staple Here Only! Staple Here

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 7,289,141 B2

DATED : October 30, 2007

INVENTOR(S): Akitoshi Yamada, et al. Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 14, "statue" should read --status--. Line 47, "statue" should read --status--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile **PATENT NO.** <u>7,289,141 B2</u>

No. of add'l. copies @ 30¢ per page

